





INCEDENTS PER HUB




INCEDENTS TIMELINE



## CCCM YEMEN FIRE INCIDENTS REPORT:


Was generated to track fire incidents at site-level, and to identify key sectoral gaps for urgent Coordination with other sectors and clusters , in order to have a better alignment and effective CCCM response. The fire Incident report is rolled out through an Activityinfo form to allow more dynamic editing by partners.

MAIN CAUSE OF FIRE




# Incidents per sub-districts


Low  
High




FIRE TIME




INJURIES TYPES




SHELTER CONDITION BEFORE THE FIRE




MAIN SITE TYPE




AFFECTED LAND AGREEMENT



WAS THE FIRE EXTINGUISHED



THE FIRE SPREAD TO OTHER SHELTERS



# FIRE DISTINGUISHERS IN THE THE AFFECTED SITES

2255


# FIRE WARDEBS IN THE AFFECTED SITES

2166


# TOTAL SHELTERS AFFECTED

205


FIRE EXTINGUISHERS IN PLACE




IF YES, WAS THE FIRE EXTINGUISHERS USED




FIRE WARDENS IN THE SITE




IF YES, WERE THE WARDENS TRAINED ON FIRE SAFTEY



DEGREE OF SHELTER AFFECTION



AFFECTED SHELTER TYPE



## SOME REASONS THE FIRE DISTINGUISHERS WEREN'T USED

- The shelter is far away from the Fire Safety Point
- The fire was controlled and put down using water truck nearby
- Fire warden was not in the site at that moment.
- The fire was controllable
- No phone coverage, couldn't contact the fire Worden to have access to them
- IDPs used sands to put out the fire
- only women were there, they couldn't use the fire extinguisher