

Annex 2 : Completed Water Quality Analysis of Representative Wells in each Reintegration Site

S/No	Site No.	Province	District	Site Name/Village	Total number of wells	# of active wells	# of non active wells	Plan for # of wells to be tested	Actual # of wells tested	Remarks
1	1	Kabul	Qarabagh	Barikab	1	1	0	1	1	Completed
2	2		Qarabagh	Alaceghan	0	0	0	0		
3	3		PD13 (urban)	Kochiabad	13	10	3	3	3	Completed
4	5	Parwan	Bagram	Khanjarkhel	60	24	36	5	5	Completed
5	8	Bamyan	Bamyan	Shashpol	9 wells and pipe scheme	9	0	4	5	Completed
6	9		Bamyan	Aqrabad	5 wells and pipe Scheme	0	5	2	3	
7	10		Bamyan	Kakrak	Pipe scheme	0	0	2	3	
8	12	Kandahar	Arghandab	Babawali	79	59	20	10	7	Completed (only 7 wells were available)
9	14	Balkh	Sholgara	Mohajer qeshlaq	13	1	12	1	1	Completed
10	16	Kunduz	Aliabad	Qizilsay	1	1	0	1	1	Completed
11	17	Faryab	Khoja Sabz Posh	Bimoghli	34	32	2	8	8	Completed
12	22	Herat	Enjil	Shgofan	4 wells and Pipe Scheme	4	0	5	3	Completed (only 3 water points were available)
13	23		Enjil	Kahdistan	15	13	2	4	4	Completed
14	26	Farah	Centre	Kurji	10	9	1	4	4	Completed
15	27	Nangarhar	Behsood	Saracha	74	53	21	6	6	Completed
16	28		Surkhrod	Shikh Mesri SMNT	102	101	1	10	10	Completed
17	29		Surkhrod	Fateh abad	240	225	15	21	21	Completed
18	37		Mohmandara	Girdi Ghuos	150	139	11	14	14	Completed
19	40	Laghman	Mihtarlam	Chilmity	48	46	2	5	6	Completed
20	41		Qarghai	Kass Aziz Khan	270	255	15	22	22	Completed
21	44	Kunar	Asadabad	Kerala	40	26	14	3	4	Completed
22	48	Paktya	Gardiz	Tera Bagh	51	43	8	5	5	Completed
Total						1051	168	136	136	