

Key figures



From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.


Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility

Water point


6,767 of assessed water points

■ **73%** functional and **27%** non-functional


Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area



Water Points with latrine/ sludge disposal within 30 feet



Bathing facility


14,643 of assessed bathing facilities

■ **98%** completed and **2%** ongoing


■ **81%** functional and **19%** non-functional

Type of bathing facility


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage



Facility door closes properly



Latrine


20,207 of assessed latrines

■ **98%** completed and **2%** ongoing


■ **83%** functional and **17%** non-functional

Type of latrine


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard



Latrine with handwashing facilities



Facility door closes properly



Key figures



From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.


Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility

Water point


807 of assessed water points

- 70% functional and 30% non-functional


Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area



Water points with latrine/ sludge disposal within 30 feet




Bathing facility


950 of assessed bathing facilities

- 97% completed and 3% ongoing
- 87% functional and 13% non-functional


Type of bathing facility



Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage



Facility door closes properly




Latrine


1,980 of assessed latrines

- 93% completed and 7% ongoing
- 74% functional and 26% non-functional


Type of latrine




Semi-permanent



Temporary



Reached as per UNHCR standard



Latrine with handwashing facilities



Facility door closes properly



Key figures



From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.


Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note - UNHCR standard for water point, latrines and bathing facility - 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility

Water point


703 of assessed water points

■ 70% functional and 30% non-functional


Type of functional water points




Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area



Water points with latrine/ sludge disposal within 30 feet




Bathing facility

1,041 of assessed bathing facilities


■ 99% completed and 1% ongoing

■ 80% functional and 20% non-functional


Type of bathing facility




Semi-permanent



Temporary




Reached as per UNHCR standard



Provision of drainage



Facility door closes properly




Latrine

1,496 of assessed latrines


■ 99% completed and 1% ongoing

■ 73% functional and 27% non-functional


Type of latrine



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly





The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations.
The information presented in this map is from various sources indicated below and not verified. It is subject to further change.

Key figures




From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility


Water point

462 of assessed water points
■ 76% functional and 24% non-functional


Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area




Water points with latrine/ sludge disposal within 30 feet




Bathing facility

561 of assessed bathing facilities
■ 99% completed and 1% ongoing
■ 87% functional and 13% non-functional


Type of bathing facility




Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage




Facility door closes properly




Latrine

889 of assessed latrines
■ 98% completed and 2% ongoing
■ 89% functional and 11% non-functional


Type of latrine




Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly





The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations.
The information presented in this map is from various sources indicated below and not verified. It is subject to further change.

Key figures



From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.


Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility

Water point


414 of assessed water points

■ 76% functional and 24% non-functional


Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area



Water points with latrine/ sludge disposal within 30 feet




Bathing facility

690 of assessed bathing facilities


■ 99% completed and 1% ongoing

■ 83% functional and 17% non-functional


Type of bathing facility



Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage



Facility door closes properly




Latrine

942 of assessed latrines


■ 98% completed and 2% ongoing

■ 84% functional and 16% non-functional


Type of latrine



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly





The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations.
The information presented in this map is from various sources indicated below and not verified. It is subject to further change.

Key figures




From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility


Water point

779 of assessed water points
■ 75% functional and 25% non-functional


Type of functional water points




Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area




Water points with latrine/ sludge disposal within 30 feet




Bathing facility

1,823 of assessed bathing facilities
■ 98% completed and 2% ongoing
■ 81% functional and 19% non-functional


Type of bathing facility



Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage




Facility door closes properly




Latrine

2,171 of assessed latrines
■ 97% completed and 3% ongoing
■ 75% functional and 25% non-functional


Type of latrine



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Latrine with lighting facility





The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations. The information presented in this map is from various sources indicated below and not verified. It is subject to further change.

Key figures




From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bating facility


Water point




Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area



Water points with latrine/ sludge disposal within 30 feet



Bathing facility




Type of bathing facility


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard




Provision of drainage



Facility door closes properly



Latrine




Type of latrine


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly





The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations. The information presented in this map is from various sources indicated below and not verified. It is subject to further change.

Key figures




From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.


Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.

Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility


Water point




Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area



Water points with latrine/ sludge disposal within 30 feet



Bathing facility




Type of bathing facility


Permanent




Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage



Facility door closes properly



Latrine




Type of latrine


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly





The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations.
The information presented in this map is from various sources indicated below and not verified. It is subject to further change.


Key figures




From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note - UNHCR standard for water point, latrines and bathing facility - 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility


Water point




Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area



Water points with latrine/ sludge disposal within 30 feet



Bathing facility




Type of bathing facility


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard




Provision of drainage



Facility door closes properly



Latrine




Type of latrine


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly





Key figures




From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bating facility


Water point

625 of assessed water points
■ 71% functional and 29% non-functional


Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area




Water points with latrine/ sludge disposal within 30 feet




Bathing facility

1,345 of assessed bathing facilities
■ 96% completed and 4% ongoing
■ 84% functional and 16% non-functional


Type of bathing facility



Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage



Facility door closes properly




Latrine

1,532 of assessed latrines
■ 94% completed and 6% ongoing
■ 93% functional and 7% non-functional


Type of latrine



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly





The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations.
The information presented in this map is from various sources indicated below and not verified. It is subject to further change.


Key figures




From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility


Water point




Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard




Located in a flood prone area



Water points with latrine/ sludge disposal within 30 feet



Bathing facility




Type of bathing facility


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage



Facility door closes properly




Latrine




Type of latrine


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly





Key figures




From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility


Water point

411 of assessed water points
■ 73% functional and 27% non-functional


Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area




Water points with latrine/ sludge disposal within 30 feet




Bathing facility

2,205 of assessed bathing facilities
■ 99% completed and 1% ongoing
■ 78% functional and 22% non-functional


Type of bathing facility



Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage




Facility door closes properly



Latrine

2,501 of assessed latrines
■ 99% completed and 1% ongoing
■ 84% functional and 16% non-functional


Type of latrine



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly





The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations. The information presented in this map is from various sources indicated below and not verified. It is subject to further change.

Key figures




From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility


Water point

256 of assessed water points
■ 76% functional and 24% non-functional


Type of functional water points




Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area




Water points with latrine/ sludge disposal within 30 feet




Bathing facility

1,168 of assessed bathing facilities
■ 98% completed and 2% ongoing
■ 78% functional and 22% non-functional


Type of bathing facility



Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage



Facility door closes properly




Latrine

1,386 of assessed latrines
■ 98% completed and 2% ongoing
■ 80% functional and 20% non-functional


Type of latrine



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities




Facility door closes properly





The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations. The information presented in this map is from various sources indicated below and not verified. It is subject to further change.

Key figures



From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.


Note – UNHCR standard for water point, latrines and bathing facility – 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility

Water point


306 of assessed water points

■ 73% functional and 27% non-functional


Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area



Water points with latrine/ sludge disposal within 30 feet



Bathing facility

267 of assessed bathing facilities

■ 99% completed and 1% ongoing


■ 95% functional and 5% non-functional

Type of bathing facility


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard



Provision of drainage



Facility door closes properly



Latrine

981 of assessed latrines

■ 99% completed and 1% ongoing


■ 97% functional and 3% non-functional

Type of latrine


Permanent



Semi-permanent



Temporary



Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly






The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations.
The information presented in this map is from various sources indicated below and not verified. It is subject to further change.

C07_C

Key figures




From 2 October to 18 November 2018, UNHCR carried out a Water, Sanitation and Hygiene (WASH) sweep assessment on water points, latrines and bathing facilities in 14 refugee camps. These include Kutupalong and Nayapara registered camps, and the Transit Centre. The assessment cover basic information on location, status, quality, the privacy of facilities and issues such as the management of menstrual hygiene and facilities for persons with specific needs. This factsheet provides a summary of key findings for camps.

Note - due to GPS precision some infrastructures might influence the analysis in terms of coverage.
Note - UNHCR standard for water point, latrines and bathing facility - 250 people/ water point, 20 people/ latrine and 20 people/ bathing facility


Water point

110 of assessed water points
■ 85% functional and 15% non-functional


Type of functional water points



Main issues with non-functional water points



Overall condition of the hand pump



Reached as per UNHCR standard



Located in a flood prone area



Water points with latrine/ sludge disposal within 30 feet



Bathing facility


356 of assessed bathing facilities
■ 99% completed and 1% ongoing
■ 77% functional and 23% non-functional

Type of bathing facility


Permanent



Semi-permanent




Temporary



Reached as per UNHCR standard



Provision of drainage



Facility door closes properly




Latrine


906 of assessed latrines
■ 99% completed and 1% ongoing
■ 95% functional and 5% non-functional

Type of latrine


Permanent



Semi-permanent



Temporary




Reached as per UNHCR standard




Latrine with handwashing facilities



Facility door closes properly





The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by the United Nations.
The information presented in this map is from various sources indicated below and not verified. It is subject to further change.